

LOCATION: 600-D

HYDRAULIC CONDITIONS: Apparent tight unconfined fractured andesite bedrock aquifer.

PERTINENT OBSERVATIONS:

No water production observed during drilling. Development indicated low water production at initial TD of 600' and subsequent TD of 705'. Borehole deepened to 880' to increase water production and justify completion.